

CASE STUDY – Macmillan House

Client:

Crossrail

Project Manager:


Costain/Skanska/Crossrail
Joint Venture

Principal Contractor:

Costain/Skanska

Value: £15K

Date: 2014



Description:

Exploratory works to inspect condition and location of main train shed steelwork within the Grade 1 Listed Building.

The works involved:

- Removal of internal finishes and brickwork to uncover steel frame in several areas
- Survey, photograph and consultation with Client to inspect steels and gather relevant information on condition and position
- Reinststate brickwork and internal plaster work and paint finishes